

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 C T H N P 1 00-000000-00 341111 45

CON'T REPORT SOURCE L 050-0213 7102080 8102480 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 While boiling down the Aerated Drains Tank (ADT) waste evaporator in preparation for drumming, level indication was suddenly lost. The Auxiliary Operator investigated and found approximately six (6) inches of water on the waste disposal building floor. No radiation monitoring system alarms were received and there was no apparent release to the environment.

09 SYSTEM CODE MA 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE XXXXX 14 COMP. SUBCODE X 15 VALVE SUBCODE Z 16

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27 Subsequent investigation revealed the cause to be a failed gasket on the discharge piping of the reboiler pump. The gasket was replaced and the liquid waste system was returned to service.

15 FACILITY STATUS E 28 % POWER 100 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operator Observation