

ENCLOSURE

DESCRIPTION OF VIOLATIONS

Yankee Atomic Electric Company
20 Turnpike Road
Westboro, Massachusetts 01581

Certain activities under your license appear to be in violation of AEC requirements. These apparent violations are considered to be of Category II severity.

1. Technical Specifications, Paragraph D.1 states, in part, "...All plant operations...shall be conducted in accordance with written procedures ..."

 - a. Yankee Operating Procedure, Primary System Water Balance, OP-4220, states, in part, "---Step by step instructions are provided on the forms to determine the primary plant accountable and unaccountable leak rate..."

Contrary to the above the calculations performed on March 2 and 3, 1974, were not accomplished in accordance with the procedures.

- b. Yankee Operating Procedure, OP8100, Establishing and Posting Controlled Areas, states, in part, "---All controlled areas shall be adequately surveyed to insure that the boundaries established completely define the controlled area---."

Contrary to the above, on March 12, 1974, the boundary established did not completely define the contaminated area identified in the New Fuel Storage Vault.

8011050 730