LICENSEE EVENT REPORT (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION) J(1)CONTROL BLOCK -0034 0 0 0 0 0 (4) In MNPIN 0 1 LICENSE NUMBER L'ON'T L 6 0 5 0 0 0 3 0 6 7 1 0 0 3 8 0 8 1 0 3 1 REPORT 8 0 (9) 0 1 SOURCE REPORT DATE 61 DOCKET NUMBER EVENT DATE EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) During normal operation, a control room operator noticed a previously 0 2 acknowledged annunciator indicating No. 24 Fan-Coil Unit was in LOCAL 0 3 control. Review of the computer alarm typer shows the FCU was unavailable 0 4 for safeguards actuation for 5 hours and 26 minutes. No effect on public 0 5 health and safety since redundant equipment was operable. Tech Spec 0 6 3.3.B.1.b applies 0 7 0 8 ġ CAUSE COMP CODE CAUSE SUBCODE VALVE COMPONENT CODE SUBCODE (13) R K (14 E (15 Z (16 (12 F B B 9 18 OCCURRENCE REVISION REPOR SEQUENTIAL REPORT NO CODE TYPE NO EVENT YEAR LER/RO 0 2 01 REPORT 8 0 0 3 8 NUMBER 31 28 32 COMPONENT NPRD-4 PRIME COMP ATTACHMENT SUBMITTED FFFFC SHUTDOW HOURS (22) ON PLANT FORMSUB SUPPLIER MANUFACTURER N 24 19 19 2 (21 A (25 Z 19 X (18) H 01 01 0 IN 01 23 (19) 25 40 43 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) Upon discovery the local control switch was returned to Personnel error. 1 0 the REMOTE position. The switch had apparently been bumped by workmen in the area; they were cautioned to exercise care. Control room operators will review the report. Consideration is being given to adding protective covers over the switches. 4 80 9 METHOD OF FACILITY (30)DISCOVERY DESCRIPTION (32 % POWER OTHER STATUS 0 0 A 31 Operator observation E (29) NA (28) 80 ACTIVITY CONTENT LOCATION OF RELEASE (36) AMOUNT OF ACTIVITY (35 RELEASED OF HELEASE Z 33 Z 34 NA NA 45 80 PERSONNEL EXPOSURES DESCRIPTION (39) NUMBER TYPE 37 Z 38 0 10 10 NA 80 PERSONNEL INJURIES DESCRIPTION (41) NUMBER 0 0 0 40 NA 80 LOSS OF OR DAMAGE TO FACILITY (4: TYPE DESCRIPTION Z NA (42) 9 8011060488 80 PUBLICITY NRC USE ONLY DESCRIPTION 45 N 44 111111 NA 68 69 80 PHONE 612-388-4767 A. A. Hunstad NAME OF PREPARER _