NAC FO	RM 366	U. S. NUCLEAR REC	ULATORY COMMISSION
		LICENSEE EVENT REPORT	EXHIBIT A
	CONTROL BLOCK:	(PLEASE PRINT OR TYPE ALL REQUIRED IN	FORMATION)
0 1	0 N T N P 1 2 0 0	- 0 0 0 0 - 0 0 3 4 1 1 1 1 LICENSE NUMBER 25 26 LICENSE TYPE	<u>1</u> ⊕ <u>1</u> 1 €
OT	REPORT L (6) 0 5 0 -	1 0 3 4 4 (7) 1 0 0 3 8 0 (8) 1 0 3 FNUMBER SS SS EVENT DATE 74 75 REPOR	1 1 8 0 9 HT DATE 30
0 2	NO. 80-21: DURING A	TEMPORARY PLANT TEST, "C" MATE STEAM IS	OLATION
0 3	VALVE DID NOT GO FULLY	CLOSED AS REQUIRED. THIS HAD NO EFFE	CT ON SAFETY
04	SINCE NO STEAM FLOW WA	AS PRESENT IN THE VALVES DURING THIS OC	CURRENCE AND
0 5	THE VALVE IS DESIGNED	TO GO SHUT WHEN THERE IS STEAM FLOW	
0 6			
07			
0 8	!		
0 9	CIDIO EIO	SUBCODE COMPONENT CODE SUBCODE TUBECO	16
	LER/RO FEVENT YEAR	SEQUENTIAL OCCURRENCE REPORT TYPE	REVISION -
	(17) REPORT 8 0 - 23		= 101
	ACTION PUTURE EFFECT SHUTDO		COMPONENT MANUFACTURER
	TOWN Z		A 5 8 5 38
110	THE CAUSE OF THIS OCCI	VARENCE IS COMPOSENT FAILURE. IMMEDIAN	E CORRECTIVE !
1111	IS STILL UNDER INVEST		RECTIVE ACTIO
112	LO DIELLO GIDAR ENTEDE.	2012 2 2012 1	
1 3			
7 8	<u></u>		
15	C 28 0 0 1 0 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2	NA DISCOVERY DESCRIP	ON ®
	CTIVITY CONTENT 12 13 ELEASED OF RELEASE AMOUNT 0:	ACTIVITY 35 LOCATION OF RELEAS	· 36
7 8	9 10 11 PERSONNEL EXPOSURES	NA 4	50
17	NUMBER O 37 Z 38 DESCRIPTION (3	NA NA	
110	PERSONNEL INJURIES NUMBER DESCRIPTION 41	NA	
7 6	LOSS OF OR DAMAGE TO FACILITY		80
1 9	Z 42 DESCRIPTION	NA	
	SSUED DESCRIPTION 45	NA LIGHT	NAC USE ONLY
		110	
7 8	NAME OF PREPARER JOHN	68 49	-3713, ext. 228