

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | P | A | B | V | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 1 | 4 | 5
7 8 9 14 15 25 28 37 40 43 46 49 52 55 58 61 64 67 70 73 76 79 82 85 88 91

0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 0 | 3 | 3 | 4 | 7 | 1 | 0 | 0 | 1 | 8 | 0 | 8 | 1 | 0 | 2 | 9 | 8 | 0 | 9
7 8 9 14 15 25 28 37 40 43 46 49 52 55 58 61 64 67 70 73 76 79 82 85 88 91

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | Durin performance of an operational surveillance test on the Main Filter Bank flow
0 3 | and ΔP requirements, both filter banks were found isolated. No fuel movement was
0 4 | taking place and the fuel building crane was on clearance; therefore, safety
0 5 | implications were minimal.

0 9 | S | H | 11 | D | 12 | Z | 13 | Z | Z | Z | Z | Z | Z | 14 | Z | 15 | Z | 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20

17 | 8 | 0 | 21 | 22 | 0 | 8 | 2 | 24 | 26 | 0 | 3 | 28 | 29 | L | 30 | 0 | 32
18 | H | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | 40 | Y | 23 | N | 24 | Z | 25 | Z | 9 | 9 | 9 | 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause of this action was due to a procedural error. The procedure did not
1 1 | address returning the filters to service, only to inform the shift supervisor of
1 2 | test completion. A procedure correction has been made to require a sign-off when
1 3 | the test is completed.

1 5 | X | 28 | 0 | 0 | 0 | 0 | 29 | Design | 30 | B | 31 | Surveillance testing | 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 6 | Z | 33 | Z | 34 | N/A | 35 | N/A | 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 7 | 0 | 0 | 0 | 17 | Z | 38 | N/A | 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 8 | 0 | 0 | 0 | 40 | N/A | 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 9 | Z | 42 | N/A | 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

2 0 | N | 44 | N/A | 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

POOR ORIGINAL

NAME OF PREPARER W. S. Lacey

PHONE 412-643-8525

8011120354

1-924

Attachment To LER 80-82/03L
Beaver Valley Power Station
Duquesne Light Company
Docket No. 50-334

No more information is required to complete this LER.