

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 NYJAF1 00-00000-0000 41111

01 REPORT SOURCE L 05000333 112480 121780

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

02 During normal operation, while conducting surveillance required by TS Table 4.2-2, water level instrument 02-3-LIS-72D switches 3 and 4 were found set at -39.5 and -41.5 inches respectively when required to be set equal to or greater than -38.0 by TS Table 3.2-2. The three (3) other instruments performing the same function were satisfactory. No significant hazard existed.

03 SYSTEM CODE SF 11 CAUSE CODE E 12 CAUSE SUBCODE E 13 COMPONENT CODE INSTRU 14 COMP. SUBCODE S 15 VALVE SUBCODE Z 16

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

04 Instrument drift is believed to be the cause. Calibration restored instrument to within TS limits. Surveillance frequency was increased to provide assurance instrument remained within specification. No additional action is required.

05 FACILITY STATUS E 28 % POWER 100 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Surveillance 32

06 ACTIVITY RELEASED 2 33 CONTENT Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

07 PERSONNEL EXPOSURES NUMBER 000 37 TYPE Z 38 DESCRIPTION NA 39

08 PERSONNEL INJURIES NUMBER 000 40 DESCRIPTION NA 41

09 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

10 PUBLICITY ISSUED N 44 DESCRIPTION NA 45

NRC USE ONLY

8012200437 W. Verne Childs S

(315) 342-3840 X207