

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | 7 8 9 | 10 11 12 13 14 15 | 16 17 18 19 20 21 22 23 24 25 | 26 27 28 29 30 | 31 32 33 34 35 | 36 37 38 39 40 | 41 42 43 44 45 | 46 47 48 49 50 | 51 52 53 54 55 | 56 57 58 59 60 | 61 62 63 64 65 | 66 67 68 69 70 | 71 72 73 74 75 | 76 77 78 79 80 | 81 82 83 84 85 | 86 87 88 89 90 | 91 92 93 94 95 | 96 97 98 99 00 | 01 02 03 04 05

CON'T  
0 1 | 7 8 9 | 10 11 12 13 14 15 | 16 17 18 19 20 21 22 23 24 25 | 26 27 28 29 30 | 31 32 33 34 35 | 36 37 38 39 40 | 41 42 43 44 45 | 46 47 48 49 50 | 51 52 53 54 55 | 56 57 58 59 60 | 61 62 63 64 65 | 66 67 68 69 70 | 71 72 73 74 75 | 76 77 78 79 80 | 81 82 83 84 85 | 86 87 88 89 90 | 91 92 93 94 95 | 96 97 98 99 00 | 01 02 03 04 05

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
0 2 | During the performance of visual inspection of accessible snubbers on safety-related  
0 3 | systems, PT 19.6.0.2-1, snubber 1-E41-2SS105, located on the HPCI system main pump  
0 4 | discharge piping was found not connected to its pipe clamp. This event did not  
0 5 | affect the health or safety of the public.  
0 6 |  
0 7 |

0 8 | Technical Specification 3.7.5, 6.9.1.9b | 80

0 9 | 7 8 9 | 10 11 12 13 14 15 | 16 17 18 19 20 | 21 22 23 24 25 | 26 27 28 29 30 | 31 32 33 34 35 | 36 37 38 39 40 | 41 42 43 44 45 | 46 47 48 49 50 | 51 52 53 54 55 | 56 57 58 59 60 | 61 62 63 64 65 | 66 67 68 69 70 | 71 72 73 74 75 | 76 77 78 79 80 | 81 82 83 84 85 | 86 87 88 89 90 | 91 92 93 94 95 | 96 97 98 99 00 | 01 02 03 04 05

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
1 0 | This event apparently occurred due to the snubber not being reconnected following  
1 1 | construction activity in the area which required disconnecting it. Upon discovery,  
1 2 | the snubber was reconnected and restored to normal operability. Investigation did  
1 3 | not reveal the nature of the construction activity or the personnel involved.

1 4 | A letter will be written to construction and plant supervisory personnel to ensure  
7 8 9 any snubbers disconnected to facilitate maintenance are reconnected following such (see

1 5 | 7 8 9 | 10 11 12 13 14 15 | 16 17 18 19 20 | 21 22 23 24 25 | 26 27 28 29 30 | 31 32 33 34 35 | 36 37 38 39 40 | 41 42 43 44 45 | 46 47 48 49 50 | 51 52 53 54 55 | 56 57 58 59 60 | 61 62 63 64 65 | 66 67 68 69 70 | 71 72 73 74 75 | 76 77 78 79 80 | 81 82 83 84 85 | 86 87 88 89 90 | 91 92 93 94 95 | 96 97 98 99 00 | 01 02 03 04 05

1 6 | 7 8 9 | 10 11 12 13 14 15 | 16 17 18 19 20 | 21 22 23 24 25 | 26 27 28 29 30 | 31 32 33 34 35 | 36 37 38 39 40 | 41 42 43 44 45 | 46 47 48 49 50 | 51 52 53 54 55 | 56 57 58 59 60 | 61 62 63 64 65 | 66 67 68 69 70 | 71 72 73 74 75 | 76 77 78 79 80 | 81 82 83 84 85 | 86 87 88 89 90 | 91 92 93 94 95 | 96 97 98 99 00 | 01 02 03 04 05

1 7 | 7 8 9 | 10 11 12 13 14 15 | 16 17 18 19 20 | 21 22 23 24 25 | 26 27 28 29 30 | 31 32 33 34 35 | 36 37 38 39 40 | 41 42 43 44 45 | 46 47 48 49 50 | 51 52 53 54 55 | 56 57 58 59 60 | 61 62 63 64 65 | 66 67 68 69 70 | 71 72 73 74 75 | 76 77 78 79 80 | 81 82 83 84 85 | 86 87 88 89 90 | 91 92 93 94 95 | 96 97 98 99 00 | 01 02 03 04 05

1 4 | 7 8 9 | 10 11 12 13 14 15 | 16 17 18 19 20 | 21 22 23 24 25 | 26 27 28 29 30 | 31 32 33 34 35 | 36 37 38 39 40 | 41 42 43 44 45 | 46 47 48 49 50 | 51 52 53 54 55 | 56 57 58 59 60 | 61 62 63 64 65 | 66 67 68 69 70 | 71 72 73 74 75 | 76 77 78 79 80 | 81 82 83 84 85 | 86 87 88 89 90 | 91 92 93 94 95 | 96 97 98 99 00 | 01 02 03 04 05

1 9 | 7 8 9 | 10 11 12 13 14 15 | 16 17 18 19 20 | 21 22 23 24 25 | 26 27 28 29 30 | 31 32 33 34 35 | 36 37 38 39 40 | 41 42 43 44 45 | 46 47 48 49 50 | 51 52 53 54 55 | 56 57 58 59 60 | 61 62 63 64 65 | 66 67 68 69 70 | 71 72 73 74 75 | 76 77 78 79 80 | 81 82 83 84 85 | 86 87 88 89 90 | 91 92 93 94 95 | 96 97 98 99 00 | 01 02 03 04 05

2 0 | 7 8 9 | 10 11 12 13 14 15 | 16 17 18 19 20 | 21 22 23 24 25 | 26 27 28 29 30 | 31 32 33 34 35 | 36 37 38 39 40 | 41 42 43 44 45 | 46 47 48 49 50 | 51 52 53 54 55 | 56 57 58 59 60 | 61 62 63 64 65 | 66 67 68 69 70 | 71 72 73 74 75 | 76 77 78 79 80 | 81 82 83 84 85 | 86 87 88 89 90 | 91 92 93 94 95 | 96 97 98 99 00 | 01 02 03 04 05

NAME OF PREPARER A.C. Tollison, Jr.

PHONE (919) 457-9521

8012300 590

U.S. NRC FORM 366 (7-77)

LICENSEE EVENT REPORT 1-80-77

ATTACHMENT

maintenance, and that approved documentation methods are utilized.