Medel / Han

Metropolitan Edisor Company Post Office Box 4800 Middletown, Pennsylvania 17057 717 944 3041 Writer i Diffect Dial Number

Tic

December 12, 1980 TLL 658

POOR ORIGINAL

Office of Inspection and Enforcement Attn: Mr. Boyce H. Grier, Director Region I U. S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, Pennsylvania 19406

Dear Sir:

Three Mile Island Nuclear Station, Unit 2 (TMI-2) Operating License No. DPR-73 Docket No. 50-320 IE Bulletin 80-23

This response is submitted as required by IE Bulletin. 80-23.

The subject bulletin, "Failures of Solenoid Valves Manufactured by Valcor Engineering Corporation" concerns a latent defect in the magnet wire which may result in dialectric breakdown and therefore coil to coil shorting.

We have determined that there are no Valcor manufactured solenoid valves used in safety related applications in the Unit 2 facility which have the P/N's designated in the bulletin. Therefore, in accordance with the requirements of the bulletin, this constitutes our complete response.

With regards to your request for manpower expenditures, a total of approximately eight (8) man-hours were expended in relation to this bulletin response.

resident and Director, TMI-2

GKH:SDC:rdh

cc: L. Barrett B. J. Snyder