

BALTIMORE GAS AND ELECTRIC COMPANY

P.O. BOX 1475
BALTIMORE, MARYLAND 21203

ARTHUR E. LUNDVALL, JR.
VICE PRESIDENT
SUPPLY

December 5, 1980

U.S. Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA 19406

Docket Nos. 50-317
50-318
• License Nos. DPR-53
DPR-69


ATTENTION: Eldon J. Brunner, Chief
Reactor Operation and Nuclear
Support Branch

Gentlemen:

This refers to your Inspection Report 50-317/80-15; 50-318/80-14,
which transmitted one item of apparent noncompliance with NRC
requirements. Enclosure (1) to this letter is a written state-
ment in reply to that item in your letter of November 7, 1980.

Should you have further questions regarding this reply, we will
be pleased to discuss them with you.

Very truly yours,



A. E. Lundvall, Jr.
Vice President-Supply

AEL/RED/gla

Enclosure (1)

8101150 565

ENCLOSURE (1)

REPLY TO APPENDIX A OF NRC INSPECTION

REPORT 50-317/80-15; 50-318/80-14

The procedure used to measure rack to rack and rack to wall clearance was inadequate. An improved procedural format set forth by CCI 217, "Plant Modification Procedures", which adds two additional levels of review has been approved and will be used for future work of this nature. This new procedural format was used for the successful repositioning of racks 1, 2, and 3.