. CONTROL BLOCK: []] [(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 A L B R F 3 2 0 0 - 0 0 0 0 0 0 0 4 1 1 1 1 1 1 0 57 CAT 58 5
TOTI SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2 With unit 3 at 99 percent steady state power, it was discovered that the "3EB"
diesel generator lube oil circulating pump was inoperable. There was no danger
[0]4 to the health or safety of the public, no significant resulting chain of events, and
0 5 no previous similar occurrence. See technical specification 3.9.B.2.
0 6
07
7 8 2 SYSTEM CAUSE CAUSE COMP. VALVE
CODE SUBCODE S
17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 32
ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURE ON PLANT METHOD HOURS 22 SUBMITTED FORM SUB. SUPPLIER MANUFACTURE MANUFACTURE OF TAKEN ACTION ON PLANT METHOD HOURS 22 SUBMITTED FORM SUB. SUPPLIER MANUFACTURE OF TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURE OF TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURE OF TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURE OF TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURE OF TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURE OF TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURE OF TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURE OF TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURE OF TAKEN ACTION ON PLANT METHOD HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURE OF TAKEN ACTION OF
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The double-row ball bearing locked. The lube oil circulating pump was replaced.
There is no recurrence control required due to low failure rate. The event was
attributed to normal end-of-life. Viking pumps, 5 gpm, Mdl GV503A.
TIEL .
7 8 9 FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVER
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) 1 6 Z (33) Z (34) NA NA NA
7 8 9 10 11 44 45 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
1 7 0 0 0 37 Z 38 NA 7 8 9 PERSONNEL INJURIES 13 NUMBER DESCRIPTION 41
1 8 0 3 0 40 NA
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA NA
PUBLICITY ISSUED DESCRIPTION (45) NA NA NA NA
NAME OF PREPARER PHONE:

LER SUPPLE ENTAL INFORMATION

BFRO-50- 296 / 80040 Technical Specification Involved 3.9.3.2
Reported Under Technical Specif ration 6.7.2.b(2)
Date of Occurrence 10/10/80 Time of Occurrence 1:00 a.m. Unit 3
Identification and Description of Occurrence:
With unit in steady state operation, it was discovered that the "3EB" diesel generator lube oil circulating pump was inoperable.
Conditions Prior to Occurrence:
Unit 1 - 98% steady state power.
Unit 2 - Scheduled refueling outage.
"Unit 3 - 99% steady state power
Action specified in the Technical Specification Surveillance Requirements me due to moperable equipment. Describe.
Required Tech. Spec. redundant systems were tested.
Apparent Cause of Occurrence:
Bearings in the oil circulating pump locked due to normal end-of-life.
Analysis of Occurrence:
There was no danger to the health or safety of the public, no damage to plant or equipment, no release of activity, and no significant resulting chain of events.

Corrective Action:

The oil circulating pump was replaced. No future corrective action is required due to low failure rate.

Failure Data:

NA

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: