1750 Chestnut Street Tower II

SEE VALUEY AUTHORITY

January 26, 1981

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 - DOCKET NO. 50-296 - FACILITY OPERATING LICENSE DPR-68 - REPORTABLE OCCURRENCE REPORT BFR0-50-296/8008 REVISION 1

The enclosed report is a supplement to my letter dated May 1, 1980, concerning the 3B diesel generator governor actuator which would not respond properly due to dirty oil. This report is submitted in accordance with Browns Ferry unit 3 Technical Specification 6.7.2.b(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. J. Green Director of Nuclear Power

Enclosure (3)
cc (Enclosure):
 Director (3)
 Office of Management Information and Program Control
 U.S. Nuclear Regulatory Commission
 Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Bill Lavallae Nuclear Safety Analysis Center Palo Alto, California 94303

Mr. R. F. Sullivan, MRC Inspector, Browns Ferry

A003