	CONTROL BLOCK:
01	A L J M F 1 2 0 0 - 10 0 0 0 0 - 10 0 3 4 1 1 1 1 1 4 5 57 CAT 58
Ç	SOURCE L 6 0 5 0 0 0 13 14 18 7 0 7 1 7 8 10 8 0 8 1 5 8 0 9
0 2	At 1544 on 7-17-80, D.G. 1C was declared inoperable when it failed to reach rated speed
0 3	and voltage within the required time (11.5 seconds actual vs 10 ± 1 seconds required).
0 4	(D.G. 2C was inoperable at this time. See LER 80-040/03L-0.) Tech. Spec 3.8.1.1.
0 5	action statement requirements were met. A similar occurrence was reported in
0 6	LER 80-034/03L-0. Health/safety of the public were not affected by this event.
0 7	
0 8	9 SYSTEM CAUSE CAUSE COMP VALVE
0 9	CODE   CODE   SUBCODE   COMPONENT CODE   SUBCODE   SUBCO
	LER/RO EVENT YEAR SEQUENTIAL REPORT NO.  17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 . 31 32
(	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
10	The cause for D.G. 1C failure to reach rated speed and voltage within the required time
11	is under investigation. D.G. IC was returned to service at 1744 on 7-17-80.
1 2	Additional information will be submitted upon completion of the investigation.
13	
14	ļ
15	STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 NA B 31 Performance of surveillance test 3
	CTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY 35  NA LOCATION OF RELEASE 36  NA NA LOCATION OF RELEASE 36
1 7	NUMBER TYPE DESCRIPTION 39 NA
1 a	PERSONNEL INJURIES NUMBER DESCRIPTION 41  O O O O O NA
(1)	LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA  NA
2 0	PUBLICITY SSUED DESCRIPTION (15) NA NA NA NA NA NA NA
1800	82 1 05 2 68 69 80 : NAME OF PREPARER W. G. Hairston, III PHONE: (205) 899-5156