U.S. NUCLEAR REGULATORY COMMISSION

REGION 111

Report No. 50-123/85003

Docket No. 50-123 License No. R-79 Safeguards Group II

Licensee: University of Missouri - Rolla School of Mines and Metallurgy Rolla, MO 65401

Facility Name: Rolla Nuclear Reactor

Inspection At: Nuclear Reactor Building, Rolla, MO

Date of Inspection: May 28-30, 1985

Date of Previous Physical Security Inspection: August 30-31, 1983

Type of Inspection: Routine, Unannounced Physical Security

Inspectors: J. R. Komeelen for G. L. Pirtle

Physical Security Inspector

9	R. Knieley	for	
B.	Drouin vsical Securi		

6/12/85 Date

612185

Approved By:

J. R. Creed, Chie Safequards Section

6/12/15 Date

Inspection Summary

Inspection on May 28-30, 1985 (Report No. 50-123/85003(DRSS)) Areas Inspected: Included a Review of Security Plan/Implementing Procedures; Security Organization; Records and Reports; Testing and Maintenance; Locks, Keys, and Combinations; Physical Barriers; Lighting; Entry/Exit - Personnel; Entry/Exit Control - Packages/SNM; Detection Aids - CAA and Communications. The Enspection involved 22.5 hours direct-inspection effort by two NRC inspectors. The inspection began during the day shift. Results: The licensee was found to be in compliance with NGC requirements within the areas examined during the inspection, except for the following

item:

Detection Aids - CAA: There were two incidents where the Reactor Building was unoccupied and the required level of security was not maintained.

ADOCK 05000

ATTACINENT CONTAINS 10 CFR 2.700(d) 1820

Two areas of concern were developed during the course of the inspection. The first concern dealt with a lack of implementing procedures to insure that badge accountability, end of normal day security checks, and key control measures were being performed. The second concern centered on the need for a critical review of the Physical Security Plan to eliminate the numerous inaccuracies, inc nsistencies and erroneous information.

(Details - 10 CFR 2.790(d) INFORMATION)

. .

-