

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

50-5A

August 20, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

HARTSVILLE NUCLEAR PLANT - REPORTABLE DEFICIENCY - ANCHOR SPACING
ON SURFACE MOUNTED PLATES (NCR HNP-A-106) SUPPLEMENTAL RESPONSE

Initial notification of the subject deficiency was made to NRC-OIE, Region II, Inspector F. A. Cantrell, on July 11, 1980. The final report was submitted on August 11, 1980. However, an inadvertant error was made in the description of the deficiency. Instead of 30 plates being installed without meeting the requirements of C. F. Braun STRIDE Specification 300-06, 56 plates were installed. This information was telephoned to NRC-OIE, Region II on August 14, 1980, to M. Thomas of your staff. If you have any questions regarding this subject, please call Jim Domer at PTS 857-2014.

J

Very truly your,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

✓

B019
S.
1/0

8008260508