



## NARRATIVE REPORT

Georgia Power Company  
Plant E. I. Hatch  
Baxley, Georgia 31513

Reportable Occurrence Report No. 50-321/1980-089.

During normal operation, 1T47-R611, one of the Drywell and Torus Temperature Recorders was found inoperative. The redundant recorder, 1T47-R612, was operating normally. This is a repetitive occurrence as last reported on Reportable Occurrence Report No. 50-321/1980-075. There were no effects upon the public health or safety due to this event.

Upon investigation the cause was found to be a stripped gear in the print drive mechanism. The gear was replaced and the recorder was returned to normal operation. The generic review did not reveal any inherent problems. This type of recorder is not used on Unit 11. Because of the poor performance of this recorder, a design change has been initiated to replace the recorder with a different model which will offer better reliability. A follow-up report will be submitted.