LICENSEE EVENT REPORT

		그게 하게 되었다. 그런 이번 사람들이 가는 사람들에 빠져가 하는 아니라 하는 사람이 되었다. 그런 나는 사람들이 되었다.
		CONTROL BLOCK: [] [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
-	1 8	1
	O 1 8	SOURCE LE GO 5 0 0 0 2 9 5 0 0 8 2 1 8 0 0 9 0 2 8 0 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
	0 2	During normal operation, while doing a surveillance on the Aux. Bldg.
- in	0 3	ventilation system, it was found that the charcoal filters serving the
	0 4	Fuel Building were not available during non refueling modes of
-	0 5	operation as described in the Zion FSAR. The health and safety of the
	0 6	public was not affected due to the fact that there were no releases to
	0 7	the atmosphere during this mode of operation.
-	0 8	80
	7 8	SYSTEM CAUSE CAUSE COMPONENT CODE COMP. VALVE SUBCODE SUBCODE SUBCODE SUBCODE
	7 8	9 10 11 12 13 18 19 20 SEQUENTIAL OCCURRENCE REPORT TYPE NO. (17) REPORT 8 0 - 0 0 6 0 1 T - 0
		NUMBER 21 22 23 24 26 27 28 29 30 31 32
		TAKEN ACTION ON PLANT METHOD HOURS (22) SUBMITTED FORM SUB. SUPPLIER MANUFACTURER FIRE FIRE FIRE FIRE FORM SUB. SUPPLIER MANUFACTURER MANUF
	1 0	Two dampers controlling the Fuel Bldg. ventilation path to the charcoal
	11	filters were improperly installed resulting in an improper flow path.
De	1 2	The dampers have been re-installed per the original design and have
in a	1 3	been temporarily modified to assure continuous charcoal operation
	1 4	during non-refueling fuel movements.
-	7 8	POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 E (23) 0 9 0 (29) NA C (31) Personnel Observation
Ž		10 12 17 44 45 46 ACTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY 35
-	1 G 7 8	PERSONNEL EXPOSURES ON MA 44 45 NA 80
-	1 7	NUMBER TYPE DESCRIPTION (39) NA PERSONNEL INJURIES NA BO
-	118	NUMBER DESCRIPTION 41 NA
-	7 8	9 11 12 BO LOSS OF ON DAMAGE TO FACILITY (43)
_	10	Z 42 NA
		PUBLICITY ISSUED DESCRIPTION 45 NRC USE ONLY
-	/ H	NA Services Fred Stahmer PHONE: 312-746-2084 Ext 353%
		PHONE: 312-746-2084 EXt 353a