

LICENSEE EVENT REPORT

CONTROL BLOCK: 011713136

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME <u>M A Y K R 1</u>										LICENSE NUMBER <u>0 0 - 0 0 0 0 0 - 0 0</u>										LICENSE TYPE <u>4 1 1 1 1</u>					EVENT TYPE <u>0 3</u>			
CATEGORY <u>01</u> CONT										REPORT TYPE <u>L</u>		REPORT SOURCE <u>L</u>		DOCKET NUMBER <u>0 5 0 - 0 0 2 9</u>					EVENT DATE <u>0 3 0 6 7 7</u>					REPORT DATE <u>0 4 0 5 7 7</u>				

EVENT DESCRIPTION (LER 77-12/34).

<u>02</u> During normal operation the alarm setpoint adjustment of the Radiation Monitor for No. <u>2</u> Steam Generator Blowdown was found defective and the alarm could not be adjusted to the correct setpoint. A redundant alarm for the channel was not available. This was the first failure of this nature associated with this equipment. The alarm setpoint control was replaced with a spare. (LER 77-12/34)																																																																															
--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

SYSTEM CODE <u>M C</u>										CAUSE CODE <u>E</u>		COMPONENT CODE <u>I N S T R U</u>										PRIME COMPONENT SUPPLIER <u>A</u>		COMPONENT MANUFACTURER <u>W 1 2 0</u>										VIOLATION <u>N</u>	
---------------------------	--	--	--	--	--	--	--	--	--	------------------------	--	--------------------------------------	--	--	--	--	--	--	--	--	--	--------------------------------------	--	--	--	--	--	--	--	--	--	--	--	-----------------------	--

CAUSE DESCRIPTION

<u>08</u> A Westinghouse Corp. Computer/Indicator Model CS10-G alarm setpoint control failed to adjust. The plastic holder attached to the control arm failed from material fatigue. <u>10</u> The control was replaced with a spare unit.																																																																															
--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

FACILITY STATUS <u>E</u>										% POWER <u>0 9 7</u>										OTHER STATUS <u>N/A</u>										METHOD OF DISCOVERY <u>A</u>										DISCOVERY DESCRIPTION <u>N/A</u>									
FORM OF ACTIVITY RELEASED <u>Z</u>										CONTENT OF RELEASE <u>Z</u>										AMOUNT OF ACTIVITY <u>N/A</u>										LOCATION OF RELEASE <u>N/A</u>																			

PERSONNEL EXPOSURES

NUMBER <u>0 0 0 0</u>										TYPE <u>Z</u>		DESCRIPTION <u>N/A</u>									
--------------------------	--	--	--	--	--	--	--	--	--	------------------	--	---------------------------	--	--	--	--	--	--	--	--	--

PERSONNEL INJURIES

NUMBER <u>0 0 0 0</u>										DESCRIPTION <u>N/A</u>									
--------------------------	--	--	--	--	--	--	--	--	--	---------------------------	--	--	--	--	--	--	--	--	--

OFFSITE CONSEQUENCES

<u>15</u> <u>N/A</u>																																																																															
----------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

LOSS OR DAMAGE TO FACILITY

TYPE <u>Z</u>										DESCRIPTION <u>N/A</u>									
------------------	--	--	--	--	--	--	--	--	--	---------------------------	--	--	--	--	--	--	--	--	--

PUBLICITY

<u>17</u> <u>N/A</u>																																																																															
----------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

ADDITIONAL FACTORS

<u>18</u> <u>N/A</u>																																																																															
----------------------	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

<u>19</u> <u>8011240 249</u> <u>4927735</u>																																																																															
---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

NAME: Edwin L. May Perisite 4/8/77 PHONE: 413-625-6140

REGULATORY INFORMATION DISTRIBUTION SYSTEM (R 3)
DISTRIBUTION FOR INCOMING MATERIAL

50-029

REC: OREILLY J P
NRC

ORG: AUTIO H A
YANKEE ATOMIC ELEC

DOCDATE: 04/05/77
DATE RCVD: 02/21/78

DOCTYPE: LETTER NOTARIZED: NO

COPIES RECEIVED
LTR 1 ENCL 1

SUBJECT:

LICENSEE EVENT REPT (RO 50-029/77-12/03L) ON 03/06/77 CONCERNING
DURING NORMAL OPERATION THE ALARM SETPOINT ADJUSTMENT OF THE
RADIATION MONITOR FOR NO 2 STEAM GENERATOR BLOWDOWN WAS FOUND
DEFECTIVE AND THE ALARM COULD NOT BE ADJUSTED TO CORRECT SETPOINT

PLANT NAME: YANKEE ROWE

REVIEWER INITIAL: XJM
DISTRIBUTOR INITIAL:

***** DISTRIBUTION OF THIS MATERIAL IS AS FOLLOWS *****

LER (BACKFIT)
(DISTRIBUTION CODE F001)

INTERNAL:

REG FILE**W/ENCL
1 & 2**W/2 ENCL

NRC PDR**W/ENCL

EXTERNAL:

LPDR'S
GREENFIELD, MA**W/ENCL

ACRS CAT B**W/O ENCL

DISTRIBUTION: LTR 6 ENCL 6
SIZE: 1P+1P

CONTROL NBR: 780520047

***** THE END *****

POOR ORIGINAL

ao4