

CONTROL BLOCK: 011419

(PLI) PRINT ALL REQUIRED INFORMATION

LICENSEE NAME: MAYKR1
LICENSE NUMBER: 00-000000-00
LICENSE TYPE: 41111
EVENT TYPE: 03
CATEGORY: 01 CONT
REPORT TYPE: L
REPORT SOURCE: L
DOCKET NUMBER: 050-00029
EVENT DATE: 062777
REPORT DATE: 080377

EVENT DESCRIPTION (LER 77-34/3L).

02 During the testing of the Pressurizer Code Safety Valves, ~~both safety valves~~ of Huntville.
03 ~~both~~ both safety valves were found open at pressures higher than allowable (PR-SV-181
04 lifted at 2511 and PR-SV-182 at 2621). A solenoid actuated relief valve was available
05 and operable. PR-SV-181 also exceeded its acceptance limits in 1975. The safety
06 ~~valves setpoint were adjusted to acceptable values.~~ (LER 77-34/3L)

SYSTEM CODE: C J
CAUSE CODE: E
COMPONENT CODE: VALVE X
PRIME COMPONENT SUPPLIER: N
COMPONENT MANUFACTURER: D 2 4 5
VIOLATION: N

CAUSE DESCRIPTION

08 Two Dresser Inc. Model 1719WA safety valves exceeded their lift pressure setpoint
09 acceptance criteria because of setpoint drift. The valves were adjusted and retested
10 to verify the lifting pressure. ~~(PR-SV-181 was set at 2481 (Cont. Additional Factors))~~

FACILITY STATUS: G
POWER: 000
OTHER STATUS: NA
METHOD OF DISCOVERY: B
DISCOVERY DESCRIPTION: NA

FORM OF ACTIVITY RELEASED: Z
CONTENT OF RELEASE: Z
AMOUNT OF ACTIVITY: NA
LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES

NUMBER: 000
TYPE: Z
DESCRIPTION: NA

PERSONNEL INJURIES

NUMBER: 000
DESCRIPTION: NA

OFFSITE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

TYPE: Z
DESCRIPTION: NA

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 (Continued from Cause Description) ~~and PR-SV-182 set at 2536~~

19 8011240 442 492773

NAME: Edwin L. May

PHONE: 614 625-0110

GPO 881

POOR ORIGINAL