



Commonwealth Edison
Zion Generating Station
Shiloh Blvd. & Lake Michigan
Zion, Illinois 60099
Telephone 312/746-2084

November 20, 1980

Mr. James G. Keppler
Regional Director
Directorate of Regulatory Operations
Region III
U.S. Nuclear Regulatory Commission
Glen Ellyn, Illinois 60137

Reference: Zion Generating Station
Docket No. 50-295/DPR-39
Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find Updated Reportable Occurrence Report No. 50-295/80-06 for Zion Generating Station. This occurrence was reported to Region III, Directorate of Regulatory Operations by telephone on 8/21/80 and by telegram/mailgram on 8/21/80. The original report was submitted Sept. 2, 1980.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 6.6.2.a.9 which states that "Performance of structures, systems, or components that requires remedial action or corrective measures to prevent operation in a manner less conservative than assumed in the accident analyses in the safety analysis report or technical specifications bases; or discovery during plant life of conditions not specifically considered in the safety analysis report or technical specifications that require remedial action or corrective measures to prevent the existence or development of an unsafe condition", requires a 14 day written report.

Very truly yours,

K. L. Graesser
Superintendent
Zion Station

A002
5
/11

KLG/tg

Enclosure: Updated Reportable Occurrence Report No. 50-295/80-06.

NOV 21 1980

8011250338

S