



Public Service Company of Colorado

16805 ROAD 19 1/2  
PLATTEVILLE, COLORADO 80651

November 25, 1980  
Fort St. Vrain  
Unit No. 1  
P-80411

Mr. Karl V. Seyfrit, Director  
Nuclear Regulatory Commission  
Region IV  
Office of Inspection and Enforcement  
611 Ryan Plaza Drive  
Suite 1000  
Arlington, Texas 76012

Reference: Facility Operating License  
No. DPR-34

Docket No. 50-267

Dear Mr. Seyfrit:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/  
80-70, Final, submitted per the requirements of Technical Specification  
AC 7.5.2(b)2.

Also, please find enclosed one copy of the Licensee Event Report for  
Reportable Occurrence Report No. 50-267/80-70.

Very truly yours,

*Don Warembourg*  
Don Warembourg  
Manager, Nuclear Production

DW/cls

Enclosure

cc: Director, MIPC

A002  
s  
1/1

REPORT DATE: November 25, 1980

REPORTABLE OCCURRENCE 80-70  
ISSUE 0

OCCURRENCE DATE: November 10, 1980

Page 1 of 2

FORT ST. VRAIN NUCLEAR GENERATING STATION  
PUBLIC SERVICE COMPANY OF COLORADO  
16805 WELD COUNTY ROAD 19 1/2  
PLATTEVILLE, COLORADO 80651

REPORT NO. 50-267/80-70/03-L-0

Final

IDENTIFICATION OF  
OCCURRENCE:

The emergency fire water pump was removed from service to repack a leaking pump gland. This situation constitutes operation in a degraded mode of LCO 4.2.6 and is reportable per Fort St. Vrain Technical Specification AC 7.5.2(b)2.

EVENT  
DESCRIPTION:

On November 10, 1980, the emergency fire water pump was reported to have excessive pump gland leakage, which did not render the pump inoperable. On November 12, 1980, while operating at 40% thermal power, the pump was taken out of service and the gland repacked.

The emergency fire water pump was out of service from 0530 hours until 1445 hours on November 12, 1980.

CAUSE  
DESCRIPTION:

The cause of this event was the removal from service of the emergency fire water pump for repacking of the pump gland while the reactor was at power.

CORRECTIVE  
ACTION:

Upon completion of the pump gland repacking, the pump was returned to service. No further corrective action is anticipated or required.

Prepared By: Richard R. Frost  
Richard R. Frost  
Technical Services Technician

Reviewed By: J. W. Gahm  
J. W. Gahm  
Technical Services Supervisor

Reviewed By: Frank M. Mathie  
Frank M. Mathie  
Operations Manager

Approved By: Don Warembourg  
Don Warembourg  
Manager, Nuclear Production