	EXHIBIT
	CONTROL SLOCK:
0 1	FILI CR PI 3 1 10 10 1- 10 10 10 10 1- 10 10 10 10 10 10 10 10 10 10 10 10 10
O I I	SQUACE L'S 0 510 - 0 1310 12 0 0 8 0 7 8 0 1 1 2 1 1 6 8 1 0 0
012	On 15 September 1980 it was discovered that samples were not obtained for the month
0 [3]	of August from Test Well #4. This created an event contrary to Environmental
OIA	Technical Specification 3.1.5. The non-collection of those samples did not result
0 5	from operation of Crystal River #3, nor is operation of the plant affected by it.
0   6	There has been no discharge of waste water from CR-3 to the referenced ponds since
3 7	August 24, 1979. This is the sixth occurrence for this well and the seventh
013	report under this specification.
019	ZIZ TO TO THE COURT OF THE COUR
ļ	THE REPORT OF THE PROPERTY OF
	The apparent cause of this event is attributed to elimination of Test Well sites
	due to canal modification construction. The elimination of Test Well #4 was
	originally reported in LER 80-011/04L-0. Test Well 4B was established on 8/16/80.
111	Sampling for September will include Test Well 4B. The revision corrects the report
	date, failure data and supplementary information of 80-040/04L-1, dated 10/24/80.
المالية	Z 3 01 01 01 01 NA B STATES 30 SECONDARY SECON
16	ZI 33 Z 32 NA LOCATION OF RELEASE 35
II L	OI OI O O Z Z 3 PROTO 39 NA
	01 01 0 100 NA
13 17	TO OFFICE TO FLOUR (I)  NA
	NAC USE ONLY  NAC USE ONLY  NAC USE ONLY
	Name of Preparer: Victor Q. Hernandy move (904) 795-6486

(SEE ATTACHED SUPPLEMENTARY INFORMATION SEEET)

8012280 524

## SUPPLEMENTARY INFORMATION

Report No .:

50-302/80-040/04L-2

Facility:

Crystal River Unit #3

Report Date:

16 December 1980

Occurrence Date:

August 7, 1980 (determined at plant site September 15, 1980).

Identification of Occurrence:

Contrary to Environmental Technical Specification 3.1.5, a representative sample was not obtained for August from Test Well #4.

Conditions Prior to Occurrence:

N/A.

Description of Occurrence:

The August sample at Well #4 was not collected because site construction activities have eliminated the well site.

Description of Apparent Cause:

The required construction activity is part of the canal modification at the Crystal River site.

Analysis of Occurrence:

The noncompliance did not result from the operation of Crystal River #3, nor is operation of the plant affected by it. There have been no discharges of waste water to the referenced ponds since August 24, 1979. Well #4 has been out of service since February 1980, resulting in a Licensee Event Report each month it is out of service.

Corrective Action:

Test Well #4B was established on August 16, 1980 to replace Test Well #4. This revision corrects the report date, corrective action, and failure data of 80-040/04L-1, dated October 24, 1980.

Failure Data:

This is the sixth report for Test Well 4 and the seventh occurrence reported under this specification.

/rc