

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

PHONE:

8102170409

LER SUPPLEMENTAL INFORMATION

BFRO-50- 296 / 8055 Technical Specification Involved 3.8.B.6 and 3.8.B.8

Reported Under Technical Specification 6.7.2.b(2)

Date of Occurrence 12/10/80 Time of Occurrence 1710 Unit 3

Identification and Description of Occurrence:

While performing SI 4.8.B.4.3, a bad electronic card was identified and CAM 3-RM-90-250 was declared inoperable. This CAM monitors unit 3 turbine building ventilation.

Conditions Prior to Occurrence:

Unit 1 at 100% power.

Unit 2 at 89% power.

Unit 3 refueling.

Action specified in the Technical Specification Surveillance Requirements met due to inoperable equipment. Describe.

Started sampling program by the chemical laboratory.

Apparent Cause of Occurrence:

Component failure.

Analysis of Occurrence:

There was no damage to plant equipment. There was no activity release, no personnel exposure or injury and no damage to the health or safety of the public.

Corrective Action:

Repaired, functionally tested and returned to service.

Failure Data:

None.

*Retention: Period - Lifetime; Responsibility - Administrative Supervisor

*Revision: 