

U.S. NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT

REGION III

Reports No. 50-282/81-06; 50-306/81-07

Docket No. 50-282
Docket No. 50-306

License No. DPR-42
License No. DPR-60

Safeguards Group IV

Licensee: Northern States Power Company
414 Nicollet Mall
Minneapolis, MN 55401

Facility Name: Prairie Island Units 1 and 2

Inspection At: Prairie Island Site, Red Wing, MN
NSP Corporate Office, Minneapolis, MN

Inspection Conducted: March 16-20, 1981

Date of Last Physical Security Inspection: October 20-24, 1980

Type of Inspection: Unannounced Physical Protection

Inspectors: Gary S. Pittle
G. L. Pittle
Physical Security Specialist

4/14/1981
Date

Gary S. Pittle
T. J. Madeda
Physical Security Specialist

4/14/1981
Date

Approved By: W. L. Fisher
for J. R. Creed, Acting Chief
Safeguards Section

4/15/81
Date

Inspection Summary

Inspection on March 16-20, 1981 (Reports No. 50-282/81-06; 50-306/81-07)
Areas Inspected: Included a review of Security Plan; Security Organization; Protected Area Physical Barriers; Vital Area Physical Barriers; Lighting, Access Control (Identification, Authorization and Badging); Access Control (Search); Access Control (Escorting); Access Control (Vital Areas); Detection Aids; Assessment Aids; Compensatory Measures; Locks, Keys, and Combinations; Records and Reports; Followup on Previous Items of Noncompliance; Followup on Unresolved Items; and Independent Inspection Effort. The inspection involved

8105010152

80 inspector-hours onsite by two NRC inspectors. The inspection began during the day shift period; 14 inspection-hours were accomplished during offshift periods.

Results: The licensee was found to be in compliance with NRC requirements within the areas examined during this inspection except for the following two items:

1. Access Control (Identification, Authorization, and Badging) - The licensee failed to conduct proper personnel screening in accordance with a security plan commitment. (Severity Level V)
2. Access Control (Vital Areas) - The licensee failed to properly control access between adjacent vital area. (Severity Level V)

All previous security related items of noncompliance were considered closed. One unresolved item was identified.

(Details 2.790(d) Information)