## LICENSEE EVENT REPORT

	LICENSEE EVENT REPORT	
•	CONTROL BLOCK:	FORMATION)
0 1 7 a	N   Y   J   A   F   1   2   0   0   -   0   0   0   -   0   0   0	4 LAT 58 5
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 13 13 3 7 0 13 2 7 8 1 3 0 4 2 SOURCE SOURCE SOURCE SOURCE SOURCE SOURCES TO SECURITIES TO SECU	6 8 1 6 FOATE 80
0 13	Refuel Floor Vent Monitor failures occurred three times on 3/27/81 and	
04	Tip is a 2/27/01 fellows the redundant monitor was operable. During	
	- 1/12/91 (which involved both monitors) building ventilation was is	
0   5	7 - 7 - 1 - 2 2 - 6 Note 28	
0 6		
0 7		
7 8	8 9 SYSTEM CAUSE CAUSE COMP. VALV	
0 9	CODE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE	16 AEVISION
	17 REPORT   8   1	O J
	ACTION FUTURE COMPLIANT SHUTDOWN HOURS 22 ATTACHMENT NPRO-4 PRIME COMPLIANT METHOD HOURS 22 SUBMITTED FORM SUB. SUPPLIER OF SU	MANUFACTURER
1 0	The first failur	e was corrected
111	by replacement of low voltage power supply parts. The second failure	was corrected
1 2	2 by replacement of the indicator. The third failure could not be dupl	icated.
1 3	3] [Investigation did not reveal any problems. Each repair was followed	by
1 4	4 [calibration.	
7 8	FACILITY STATUS 30 METHOD OF DISCOVERY DESCRI	PTION 3
7 8	5 E 28 1 0 0 29 NA B 31 Surveillance  3 3 44 45 46 Surveillance	50
1 6	RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)  6	55 00
1 7	7 O O O O TYPE DESCRIPTION OF NA	30
1 3	NUMBER DESCRIPTION (41) NA	30
7	LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA	40
1 10	8 9 10	NRC USE ONLY
2 0	DESCRIPTION (45) NA NA S8 69	111111111
1050	3 9 20 P	-342-3840