



Portland General Electric Company
 Trojan Nuclear Plant
 P.O. Box 439
 Rainier, Oregon 97048
 (503) 556-3713

50-344



March 4, 1981
 JPY-179-81

Mr. R. H. Engelken, Director
 U.S. Nuclear Regulatory Commission
 Region V
 Suite 202, Walnut Creek Plaza
 1990 N. California Blvd.
 Walnut Creek, CA 94956



Dear Mr. Engelken:

This is an update on my previous letter, dated December 4, 1980, concerning nonfunctional fire barriers.

All of the three-hour fire penetrations on the enclosed list were repaired and returned to service by February 19, 1981.

Sincerely,

C. A. Olmstead

for C. P. Yundt
 General Manager

CAO RB
 CPY/CAO/RQR:bb
 Attachment

c: LER Distribution List

*A002
 1/1*

F 8103170474

81-52

P = PENETRATION

C = CONDUIT

NONFUNCTIONAL FIRE BARRIERS

Page 1 of 2

TAG #	LOCATION	TYPE	DEFICIENCIES	REMARKS
P-1	Service Water Pump Room (West Wall)	Elect. Wall Penetration	Needs Capped	Note 1 <i>REPAIRED WEEK OF 16 FEB 91</i>
P-8	Cable Spreading Room (West Wall Floor)	Cable Tray Penet.	Backside Needs Foam	Note 1 "
P-9	Cable Spreading Room (West Wall)	Cable Tray Penet.	Backside Needs Foam	Note 1 "
P-10	Cable Spreading Room (West Wall Floor Slab)	Cable Tray Penet.	Backside Needs Foam	Note 1 "
P-11	Cable Spreading room (North Wall Ceiling)	Cable Tray Penet.	Needs Foam	Note 1 "
P-12	Cable Spreading Room (North Wall Ceiling)	Cable Tray Penet.	Needs Foam	Note 1 "
P-13	Cable Spreading Room	Core for	Needs Foam	Note 1 "
P-14	Cable Spreading Room (To C-41B Panel in Control Rm)	Elect. Cable	Needs Foam	Note 2 "
P-15	C-41B Panel in Control Rm.	Elect. Cable	Needs Foam	Note 2 "
P-16	C-41B Panel in Control Rm.	Elect. Cable	Needs Foam	Note 2 "
P-17	C-41B Panel in Control Rm.	Elect. Cable	Needs Foam	Note 2 "
P-18	C-41B Panel in Control Rm.	Elect. Cable	Needs Foam	Note 2 "
P-19	Cable Spreading Room to C19 in Control Room	Elect. Cable	Needs Foam	Note 3 "
P-20	C-19 Panel Control Room	Elect. Cable	Needs Foam	Note 4 "

P - PENETRATION

C - CONDUIT

NONFUNCTIONAL FIRE BARRIERS

Page 2 of 2

TAG #	LOCATION	TYPE	DEFICIENCIES	REMARKS
P-21	Control Bldg. Elect. Aux. Room Floor Slab 'N' Line	Cpre Drill	Needs Grout	Regouted week of November 24, 1980
P-22	Floor Slab 'H' Line	Core Drill	Needs Grout	Regouted week of November 24, 1980
P-23	East Wall	Core Hole	Needs Grout	Regouted week of November 24, 1980
P-24	East Wall	Pipe Penetration	Needs Grout and Cap	Capped and regouted week of November 24, 1980

Note 1 - Electrical penetrations were made due to RDC 79-51, installation of additional area radiation monitors.

Note 2 - Electrical penetrations were made due to RDC 78-49, installation of high range noble gas monitors.

Note 3 - Electrical penetrations were made due to RDC 79-63, auxiliary feedwater low suction pressure trip modification.

Note 4 - Electrical penetrations were made due to RDC 79-99, auxiliary feedwater flow indication installation.