
## 1750 Chestnut Street Tower II

April 22, 1981

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:



The enclosed report provides details concerning the inoperability of the auxiliary building ventilation system particulate radiation monitor due to failure of its normal speed paper advance drive motor. This event placed Sequoyah unit 1 in action statement 44 of limiting condition for operation 3.3.3.10 and is reported under Sequoyah unit 1 Technical Specification 6.9.1.13.b.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. J. Green Director of Nuclear Power

Enclosure (3) cc (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Mr. Bill Lavallee Nuclear Safety Analysis Center Palo Alto, California 94303

NRC Inspector, Sequoyah

4001/1