

## LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK:										(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)									
<div> <div>01</div> <div>ARANO</div> <div>00-000000-00</div> <div>03411111</div> <div>05</div> </div>										<div> <div>LICENSEE CODE</div> <div>LICENSE NUMBER</div> <div>LICENSE TYPE</div> <div>CAT</div> <div>SR</div> </div>									
<div> <div>01</div> <div>REPORT SOURCE</div> <div>0605000313070227181003251811</div> <div>09</div> </div>										<div> <div>DOCKET NUMBER</div> <div>EVENT DATE</div> <div>REPORT DATE</div> </div>									
<div> <div>02</div> <div>During a review of a weekly list of procedures, it was discovered that</div> </div>																			
<div> <div>03</div> <div>the Diesel Fire Pump Battery Bank surveillance test was not completed</div> </div>																			
<div> <div>04</div> <div>within the grace period. The surveillance was immediately performed and</div> </div>																			
<div> <div>05</div> <div>the battery bank proved operable. The following LER's were similar based</div> </div>																			
<div> <div>06</div> <div>on failure to complete a surveillance on time: 313/76-19, 76-23, 77-11,</div> </div>																			
<div> <div>07</div> <div>77-16, 78-31, 79-29, 79-36. Reportable per T.S. 6.12.3.2.b.</div> </div>																			
<div> <div>08</div> <div></div> </div>																			
<div> <div>09</div> <div> <div> <div>SYSTEM CODE</div> <div>CAUSE CODE</div> <div>CAUSE SUBCODE</div> <div>COMP CODE</div> <div>VALVE SUBCODE</div> </div> <div> <div>LAIB</div> <div>11</div> <div>12</div> <div>13</div> <div>14</div> <div>15</div> <div>16</div> </div> </div> </div>																			
<div> <div>17</div> <div>LER/HO REPORT NUMBER</div> <div>811</div> <div>18</div> <div>19</div> <div>20</div> <div>21</div> <div>22</div> <div>23</div> <div>24</div> <div>25</div> <div>26</div> <div>27</div> <div>28</div> <div>29</div> <div>30</div> <div>31</div> <div>32</div> </div>																			
<div> <div> <div>EVENT YEAR</div> <div>SEQUENCE REPORT NO.</div> <div>OCCURRENCE CODE</div> <div>REPORT TYPE</div> <div>REVISION NO.</div> </div> <div> <div>811</div> <div>1</div> <div>004</div> <div>1</div> <div>0</div> </div> </div>																			
<div> <div> <div>ACTION TAKEN</div> <div>FUTURE ACTION</div> <div>EFFECT ON PLANT</div> <div>SHUTDOWN METHOD</div> <div>HOURS</div> <div>ATTACHMENT SUBMITTED</div> <div>NPRD-4 FORM 504</div> <div>PRIME COMP. SUPPLIER</div> <div>COMPONENT MANUFACTURER</div> </div> <div> <div>H</div> <div>Z</div> <div>Z</div> <div>Z</div> <div>0000</div> <div>N</div> <div>N</div> <div>Z</div> <div>Z191919</div> </div> </div>																			
<div> <div>10</div> <div>Personnel assigned to perform the surveillance test failed to notify their</div> </div>																			
<div> <div>11</div> <div>supervisor that the procedure could not be completed during the shift.</div> </div>																			
<div> <div>12</div> <div>Supervisory review did not occur until after the required completion date.</div> </div>																			
<div> <div>13</div> <div>In the future, supervisors will review assigned procedures before the due</div> </div>																			
<div> <div>14</div> <div>date. The "Battery Bank" was demonstrated operable on 2/27/81 by comple-</div> </div>																			
<div> <div>15</div> <div>tion of the required surveillance checks.</div> </div>																			
<div> <div> <div> <div>FACILITY STATUS</div> <div>% POWER</div> <div>OTHER STATUS</div> <div>MENTIONED IN DISCOVERY</div> <div>DISCOVERY DESCRIPTION</div> </div> <div> <div>H</div> <div>0000</div> <div>Refueling</div> <div>LB</div> <div>Procedure Review</div> </div> </div> </div>																			
<div> <div> <div>ACTIVITY RELEASED OF RELEASE</div> <div>AMOUNT OF ACTIVITY</div> <div>LOCATION OF RELEASE</div> </div> <div> <div>Z</div> <div>Z</div> <div>NA</div> <div>NA</div> </div> </div>																			
<div> <div> <div>PERSONNEL EXPOSURES NUMBER</div> <div>TYPE</div> <div>DESCRIPTION</div> </div> <div> <div>000</div> <div>Z</div> <div>NA</div> </div> </div>																			
<div> <div> <div>PERSONNEL INJURIES NUMBER</div> <div>DESCRIPTION</div> </div> <div> <div>000</div> <div>NA</div> </div> </div>																			
<div> <div> <div>LOSS OF OR DAMAGE TO FACILITY TYPE</div> <div>DESCRIPTION</div> </div> <div> <div>Z</div> <div>NA</div> </div> </div>																			
<div> <div> <div>PUBLICITY ISSUED</div> <div>DESCRIPTION</div> </div> <div> <div>N</div> <div>NA</div> </div> </div>																			
<div> <div> <div>NAME OF PREPARER</div> <div>PHONE</div> </div> <div> <div>L. S. Bramlett</div> <div>501/968-2519</div> </div> </div>																			

8103310590