## LICENSEE EVENT REPORT

CONTROL BLOCK: PLEASE	PRINT OR TYPE ALL REQUIRED INFORMATION
0 1   C 0   F   S   V   1   2   0   0   -   0   0   0   0   -   0   0	0 0 3 4 1 1 2 0 4 57 CAT 58 5
7 8 60 61 DOCKET NUMBER 68 69 EV	3 1 8 1 8 0 4 3 0 8 1 9 ENT DATE 74 75 REPORT DATE 80
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)	(NOS 41 NOS 40 and 1
0 2 During other than shutdown conditions, three cl	ass I shubbers (BUS 41, BUS 49, and
0 3 HOS 57) were removed from service for modificat	
o 4 seismic analysis program. This is a degraded m	ode of LCO 4.3.10 and is reportable
o   5   per Fort St. Vrain Technical Specification AC 7	
[3]6] No affect on public health or safety. Similar	reports RO 80-03, 80-06, 80-27, 80-61,
0 7 and 80-65.	
7 8 9	80
SYSTEM CODE CODE SUBCODE COMPONENT  A D 11 X 12 Z 13 LS U P 0	1-1-10 1-10
17 REPORT NUMBER 21 22 23 24 26 27	CODE TYPE NO.  O 3   L   O    28 29 30 31 32  COMPONENT NARD-4 PRIME COMP. COMPONENT MANUFACTURER
X 18 Z 19 Z 20 Z 21 10 0 0 0	Y 3 N 2 LA 3 12 9 9 9 26
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  Shubbers were taken out of service for modifications	tions required by the 2 inch and under
seismic analysis program. Snubbers were return	ed to service upon completion of modi-
fication.	
FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
15 X 28 10 0 12 13 Training Starts   A 30 45	Operator Observation
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35	LOCATION OF RELEASE 36
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39	80
7 0 0 0 0 37 Z 38 N/A	80
PERSONNEL INJURIES NUMBER DESCRIPTION 41	
LOSS OF OR DAMAGE TO FACILITY 43	80
7 8 9 10 N/A	30
ISSUED DESCRIPTION 45	NRC USE ONLY
1 8 9 10	68 69 80 ±
106030 277	PHONE: (303) 763-2224