APPENDIX A

NOTICE OF VIOLATION

Connecticut Yankee Atomic Power Company

Docket No. 50-213

Based on the results of an NRC inspection conducted on July 28, 1980 of the shipment of radioactive waste which was shipped from your facility on or about July 25, 1980, it appears that one of your activities was not conducted in full compliance with federal regulations and the conditions of your NRC facility license DPR-61 as indicated below.

10 CFR 71.5 prohibits delivery of licensed material to a carrier for transport unless the licensee complies with applicable regulations of the Department of Transportation in 49 CFR Parts 170-189.

49 CFR 173.392(c)(7) requires, in part, that the transport vehicle must be placarded with the placards prescribed in accordance with paragraph 172.500 of this subchapter, as appropriate. 49 CFR 172.504 requires, in part, that each motor vehicle...must be placarded on each end and each side....

Contrary to the above, on or about July 25, 1980, the licensee delivered packages of low specific activity (LSA) radioactive licensed material to a carrier for transport to the waste burial site on a tractor-trailer assigned for sole use, and upon arrival at the burial site on July 28, 1980, the vehicle was not placarded as required on the front and of the trailer or the front end of the tractor.

This is a Severity Level IV noncompliance.

U.S. NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT

Region I

Report No.	50-213/80-16	
Docket No.	50-213	
License No.	DPR-61 Priority	Category
Licensee:	Connecticut Yankee Atomic Power Company	
	P.O. Box 270	
	Hartford, Connecticut 06101	
Facility Nam	ne: Haddam Neck	
Inspection a	at: Barnwell, South Carolina Burial Site	
Inspection o	conducted: July 28, 1980	
Inspectors: (See Attached Report Cover Sheet)		
		date signed
		date signed
		date signed
Approved by	: (See Attached Report Cover Sheet)	
		date signed

Inspection Summary:

(See Attached Report Cover Sheet)