

1981 JAN 6

December 31, 1980

In reply, please
refer to LAC-7296

DOCKET NO. 50-409

U. S. Nuclear Regulatory Commission
ATTN: Mr. Darrell G. Fisenhut, Director
Division of Licensing
Office of Nuclear Reactor Regulation
Division of Operating Reactors
Washington, D. C. 20555

SUBJECT: DAIRYLAND POWER COOPERATIVE
LA CROSSE BOILING WATER REACTOR (LACBR)
PROVISIONAL OPERATING LICENSE NO. DPR-45
POST TMI REQUIREMENTS

- References:
- (1) NRC Letter, Eisenhut to All Operating Reactors, dated October 31, 1980.
 - (2) DPC Letter, Linder to Denton, LAC-6769, dated January 31, 1980.
 - (3) DPC Letter, Linder to Eisenhut, LAC-7112, dated September 3, 1980.

Gentlemen:

Your issuance of NUREG-0737 (Reference 1) summarized the requirements for Post Three Mile Island action items. Our responses to the previous guidelines of NUREG-0578 (Reference 2) and NUREG-0660 (Reference 3) together with additional submittals previously made, represent our contemplated actions and our requests for exemptions.

The refueling outage currently in progress combined with the ASLB hearings on site liquefaction have occupied the attention of staff personnel which are completing information requested in NUREG-0737. We will submit the required documentation by the dates listed below. As these requested extensions do not represent delays in completion of modifications, no compensating safety actions are proposed for the interim.


<u>Item</u>	<u>Action</u>	<u>Revised Date</u>
I.A.11	STA training to Category B as identified in previous submittals is completed. A long-term program description as required by NUREG-0737 remains to be submitted.	January 15, 1981

<u>Item</u>	<u>Action</u>	<u>Revised Date</u>
II.B.4	Prepare training program for mitigating core damage and have program available for review.	January 15, 1981
II.E.4.2	Review of containment pressure setpoint for isolation function.	February 2, 1981
II.K.3.17	Report on outages of emergency core cooling systems.	January 15, 1981
II.K.3.30	Schedule a meeting for review of small break LOCA model.	February 2, 1981
II.K.3.44	Provide results of evaluation of anticipated transients with single failure.	January 15, 1981
III.A.2.1	Submit revised radiological emergency response plan.	February 2, 1981
III.D.3.3	Complete training on procedures governing use of single channel analyzer.	January 15, 1981
III.D.3.4	Review of control room habitability.	February 2, 1981

If there are any questions regarding this letter, please let us know.

Very truly yours,

DAIRYLAND POWER COOPERATIVE



Frank Linder, General Manager

FL:JDP:af

cc: J. G. Keppler, Reg. Dir., NRC-DRC III
NRC Resident Inspectors