GULF STATES UTILITIES COMPANY

AREA CODE 713 838-8631

December 2, 1980

RBG - 9153 Files G9.5, G9.33.1 IN

N

Mr. Karl V. Seyfrit, Director
U.S. Nuclear Regulatory Commission
Region IV, Office of Inspection
and Enforcement
611 Ryan Plaza Drive
Suite 1000
Arlington, TX 76011

Dear Mr. Seyfrit:

River Bend Station - Units 1 & 2
Refer to: RIV
Docket Nos. 50-458/I&E Bulletin 80-16
50-459/I&E Bulletin 80-16

This response is the supplement referred to in our letter of September 5, 1980, which addressed our A/E's (S&W) scope of supply. Our NSSS vendor (G.E.) has recently completed its investigation of "Potential Misapplication of Rosemount, Inc. Models 1151 and 1152 Pressure Transmitters With Either "A" or "D" Output Codes" as stated in I&E Bulletin No. 80-16, and has identified the following instrument numbers (from the Master Parts List) as questionable:

C11-N054	E22-N050
C71-N050	E22-N054
E12-N052	E22-N056
E12-N055	E31-N080
E12-N056	E31-N081
E21-N051	E31-N083
E21-N052	E31-N084
E21-N053	E31-N085

To further address the instruments listed above, G.E. has committed to perform an internal design review during the first quarter of 1981, and to document the results at the end of that quarter.

Mr. Karl V. Seyfrit, Director December 2, 1980 Page 2

It should be noted that none of the questionable instruments are installed and if any are found to be unacceptable, they will be dispositioned by the issuance of a Field Disposition Instruction (FDI).

Approximately 800 total man-hours have been consumed to date addressing I&E Bulletin 80-16. GSU will report on the results of G.E.'s internal design review and update the total man-hours entailed by May 1, 1981.

Sincerely,

E. Linn Drapes eggEB

E. Linn Draper, Jr. Vice President-Nuclear Technology

ELD/RJK/mea

cc: Director, Division of Reactor
Construction Inspections
Office of Inspection & Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555