

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401
400 Chestnut Street Tower II

January 20, 1981

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

HARTSVILLE AND PHIPPS BEND NUCLEAR PLANTS - REPORTABLE DEFICIENCIES -
HTRD-50-518, -519, -520, -521/81-02, PBRD-50-553, -554/81-02 AND HTRD-50-518,
-519, -520, -521/81-03, PBRD-50-553, -554/81-03

The first interim reports on the subject deficiencies were submitted on
January 12 and January 9, 1981, respectively. Due to an inadvertent error,
the deficiency numbers on the two reports were incorrect.

1. For the report entitled "Pressure Drop in Essential Service Water Piping,"
dated January 12, 1981, the deficiency numbers should read:

HTRD-50-518, -519, -520, -521/81-02
PBRD-50-553, -554/81-02

2. For the report entitled "SGTS Design Deficiency," dated January 9, 1981,
the deficiency numbers should read:

HTRD-50-518, -519, -520, -521/81-03
PBRD-50-553, -554/81-03

Please note that the only difference occurring is the year to which the
deficiency number applies (1981 instead of 1980).

If you have any questions, please get in touch with J. A. Damer at FTS
857-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

cc: Mr. Victor Stello, Director ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

B019
S
160

8101290 489
S