



SACRAMENTO MUNICIPAL UTILITY DISTRICT □ 6201 S Street, Box 15830, Sacramento, California 95813; (916) 452-3211

February 20, 1981

Mr. R. H. Engelken, Director
Region V Office of Inspection & Enforcement
1990 North California Boulevard
Walnut Creek Plaza, Suite 202
Walnut Creek, CA 94596



Re: Operating License DPR-54
Docket No. 50-312
Reportable Occurrence 81-8

Dear Mr. Engelken:

In accordance with Technical Specifications Section 6.9.4.1(i) and Regulatory Guide 1.16, Revision 4, Section C.2.a(9), the Sacramento Municipal Utility District reports the following Licensee Event Report Number 81-8.

During preventative maintenance on ITE Electrical Breakers Model K-600, a breaker was observed not to trip. An investigation revealed that a wire had slipped out of a terminal lug from the tripping coil. The coil wire was measured to be No. 20 gauge and the mating lug was for 16-14 gauge wire. A check of other ITE electrical breakers indicated that the problem is generic to these breakers.

Mr. R. Colombo discussed details of this problem with the Resident NRC Inspector, H. Canter.

A complete report will be submitted to your office within fourteen days.

Sincerely,

R. J. Rodriguez
Manager Nuclear Operations

RJR:RWC:rm

A002
S/11

5 810227, 817

