



**Commonwealth Edison**  
 Zion Generating Station  
 Shiloh Blvd. & Lake Michigan  
 Zion, Illinois 60099  
 Telephone 312/746-2084

DSB

April 8, 1981

Mr. James G. Keppler  
 Regional Director  
 Office of Inspection and Enforcement  
 Region III  
 U.S. Nuclear Regulatory Commission  
 Glen Ellyn, Illinois 60137



Reference: Zion Generating Station  
 Docket No. 50-295/DPR-39  
 Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find Reportable Occurrence Report No. 50-295/81-08 for Zion Generating Station. This occurrence was reported to Region III, Directorate of Regulatory Operations by telephone on 3/26/81 and by telegram/mailgram on 3/26/81.

This report is submitted to you in accordance with the requirements of the Technical Specifications. Section 6.6.2.a.9 which states that performance of structures, systems, or components that requires remedial action or corrective measures to prevent operation in a manner less conservative than assumed in the accident analyses in the safety analysis report or technical specifications bases; or discovery during plant life of conditions not specifically considered in the safety analysis report or technical specifications that require remedial action or corrective measures to prevent the existence or development of an unsafe condition require a 14 day written report.

Very truly yours,  
*K. L. Graesser*  
 K. L. Graesser  
 Superintendent  
 Zion Station

cc: J. Kohler/J. Waters

Enclosure: Reportable Occurrence Report No. 50-295/81-08

A002  
 S111  
 APR 10 1981

810420039a  
 S