



LER 81-011/03L-0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (Continued)

door was closed at approximately 0255, and the air lock was returned to service at 0420 on 3-21-81 following repairs and verification of proper operation.

The individual involved was instructed in the proper method of operating the air lock.