

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
---	---

REPORT SOURCE

L	6	0	5	0	0	0	3	2	7	7	0	4	0	9	8	1	8	0	5	0	1	8	1	9
60	61	DOCKET NUMBER						68	69	EVENT DATE						74	75	REPORT DATE						80

0 2 | With Unit 1 at 97%, the turbine building sump discharge radiation monitor was declared

0 3 | inoperable when its sample pump motor breaker tripped. The plant entered action

0 4 | statement 32 of LCO 3.3.3.9. There was no effect upon public health or safety.

0 5 | No previous occurrences.

0 6 |

0 7 |

0 8 |

SYSTEM CODE M C 11		CAUSE CODE X 12		CAUSE SUBCODE Z 13		COMP. SUBCODE Z 15		VALVE SUBCODE Z 16	
EVENT YEAR 8 1		SEQUENTIAL REPORT NO. 0 4 3		OCCURRENCE CODE 0 3		REPORT TYPE L		REVISION NO. 0	
ACTION TAKEN X 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0	
ATTACHMENT SUBMITTED N 23		NPRD-4 FORM SUB. N 24		PRIME COMP. SUPPLIER Z 25		COMPONENT MANUFACTURER Z 9 9 9 9			

1 0 | The circuit breaker tripped on high current. The motor was checked, verified to be
1 1 | operable, and returned to service. The monitor was out of service for less than one
1 2 | hour. If additional trips occur, a change to the breaker trip setpoint may be
1 3 | warranted. At present, no corrective action is planned.
1 4 | _____

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	G	28	0	9	7	29	NA	44
7	8	9	10	11	12	13	14	15	16
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	6	Z	33	Z	34	NA	44	45	80
7	8	9	10	11	12	13	14	15	16
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION			
1	7	0	0	0	37	Z	38	NA	80
7	8	9	10	11	12	13	14	15	16
PERSONNEL INJURIES		NUMBER		DESCRIPTION					
1	8	0	0	0	40	NA	41	42	80
7	8	9	10	11	12	13	14	15	16
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION					
1	9	Z	42	NA	43	44	45	46	80
7	8	9	10	11	12	13	14	15	16
PUBLICITY		ISSUED		DESCRIPTION					
2	0	N	44	NA	45	46	47	48	80
7	8	9	10	11	12	13	14	15	16

Phone (615) 842-8317

8105060339