APPENDIX A

NOTICE OF VIOLATION

Public Service Company of New Hampshire Seabrook Unit 1 Docket No. 50-443 License No. CPPR-135

As a result of the inspection conducted February 2-27,1981, and in accordance with the Interim Enforcement Policy, 45FR66754 (October 7,1980), the following violation was identified:

10CFR50, Appendix B, Criterion V states, in part, that: "Activities affecting quality shall be...accomplished in accordance with (the prescribed) instructions, procedures, or drawings."

The Seabrook Station PSAR for Units 1 and 2 states, in part, in paragraph 17.1.5 that: "Each organization is required to perform their respective quality related activities covered by this program in accordance with documented instructions, procedures, or drawings."

United Engineers and Constructors (UE&C) Specification 006-18-1, Revision 5, states in part in paragraph 4.2.2, that: "Anchor bolts with nominal sizes greater than 2 inches in diameter shall be examined by magnetic particle on the final machined parts."

Contrary to the above, as of February 9,1981, the eight 3 inch diameter anchor bolts included as part of the Embedded Reactor Supports (ERS-1 and ERS-2), were installed and partially embedded without a magnetic particle examination having been conducted on the threaded bolt lengths.

This is a severity Level V violation (Supplement II).

Pursuant to the provisions of 10CFR2.201, Public Service Company of New Hampshire is hereby required to submit to this office within twenty-five days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; (3) the date when full compliance will be achieved. Under the authority of Section 182 of the Atomic Energy Act of 1951, as amended, this response shall be submitted under oath or affirmation.

Dated

MAR 1 8 1981

Eldon J. Brunner, Chief, Projects Branch #1, Division of Resident and Project Inspection

810506 499