



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION IV  
811 RYAN PLAZA DRIVE, SUITE 1000  
ARLINGTON, TEXAS 76011

JUN 03 1981

In Reply Refer To:  
Docket No. 50-128/81-01



Texas A&M University  
ATTN: Dr. Robert R. Berg, Director  
Office of University Research  
College Station, TX 77843

Gentlemen:

This letter refers to the May 7-8, 1981, routine inspection conducted by Mr. R. A. Caldwell of NRC's Region IV Office. The activities inspected were those that are authorized under NRC License No. R-83. It further refers to the discussion that he had with you concerning his findings at the conclusion of the inspection.

The inspection related to your program and activities designed to protect against industrial sabotage and to safeguard special nuclear material. The inspection was based on the applicable provisions of Title 10, Part 50, of the Code of Federal Regulations, entitled, "Licensing of Production and Utilization Facilities," within Part 73 entitled, "Physical Protection of Plants and Materials," and the specific requirements of NRC License No. R-83. The inspection consisted of selective examinations of procedures and records, personnel interviews, and observations by the inspector.

No violations of NRC requirements, within the scope of this inspection, were identified.

The documentation of findings of your control and accounting procedures for safeguarding special nuclear materials and your facility's security procedures are exempt from disclosure. This exemption is covered within Title 10 CFR, Part 2, Section 2.790(d), entitled, "Rules of Practice for Domestic Licensing

10 CFR 2.790 (d) INFORMATION  
IS CONTAINED IN THIS REPORT.

1E02  
5/11


Q  
8106090 308

Texas A&M University

-2-

Proceedings." Therefore, the inspection report will not be placed in the Public Document Room and distribution will be limited. If you have any questions concerning this report, we will be pleased to discuss them with you.

Sincerely,



G. D. Brown, Chief  
Technical Inspection Branch

Enclosure:  
IE Inspection Report No. 50-128/81-01