



Carolina Power & Light Company

H. B. ROBINSON STEAM ELECTRIC PLANT
Post Office Box 790
Hartsville, South Carolina 29550

June 9, 1981



Robinson File No: 2-0-4-a-3

Serial:RSEP;81-902

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET 50-261
LICENSE NO. DPR-23
LICENSEE EVENT REPORT 81-013, REVISION 1

Dear Mr. O'Reilly:

In accordance with Section 6.9.2 of the Technical Specifications for the H. B. Robinson Steam Electric Plant, Unit 2, the enclosed Licensee Event Report Revision is submitted. The original report, May 15, 1981, described six containment isolation valves which were not being tested in a manner which fully satisfied Technical Specification 4.4.2.a. On May 10, 1981, while revising the Periodic Test which tests the containment isolation valves, two additional valves were found to fall in the same category as the six valves already reported. This revision contains a complete description of the event. New information is indicated by a vertical bar in the right hand margin. This report, therefore, supercedes and should replace all copies of the original LER. This report fulfills the requirements for a written report within thirty (30) days of a reportable occurrence and is in accordance with the format set forth in NUREG-0161, July, 1977.

Very truly yours,

R. B. Starkey, Jr.
General Manager

H. B. Robinson S.E. Plant

FMG/tm

Enclosure

cc: R. A. Hartfield (3)
V. Stello (30)

8106150145

5