LICENSEE EVENT REPORT

- 6	LICENSEE EVENT REPORT
•	CONTROL BLOCK:
0 1 8	N J S G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5 CAT 56
CON'T 0 1 7 8	SOURCE L 6 0 5 0 0 0 2 7 2 7 0 5 1 2 8 1 8 0 6 0 8 8 1 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 At 1120 hours on May 12, 1981, Action Statement 3.6.2.3 was entered due to
	13 Containment Fan Coil Unit not being capable of a shift from low service water flow
0 3	to high service water flow. This occurrence constitutes operation in a degraded mode
0 4	IAW Technical Specification 6.9.1.9b.
0 5	TAW Technical Specification 6.9.1.95.
0 6	
0 7	
0 8	80
0 9	SYSTEN CAUSE CODE SUBCODE S C 11 E 12 B 13 V A L V E X 14 A 15 G 16
	17 REPORT NO. CODE TYPE NC. NC
	TAKEN ACTION ON PLANT SHUTDOWN HOURS 22 ATTACHMENT FORM SUBMITTED FORM SUBMITTED FORM SUBMITTED SUBMITTED FORM
10	Investigation disclosed that valve 13SW65 would not function due to the stem being
111	Separated from the actuator. Separation was caused by a cracked trunnion block plug.
1 2	The trunnion block plug was replaced. Additional valve internals were replaced as a
1 3	preventive maintenance measure. 13 Containment Fan Coil Unit was tested satisfactorily.
14	Action Statement 3.6.2.3 was terminated at 2335 hours on May 13, 1981.
15	FACILITY STATUS E 28 0 9 9 9 29 N/A METHOD OF DISCOVERY DESCRIPTION 32 A 30 Operator Observation 80
	ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36 N/A N/A 80
1 7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 O O O O O O O O O O O O O O O O O O O
1 8	NUMBER DESCRIPTION 41
7 8	LOSS OF OR DAMAGE TO FACILITY 43
1 9	Z 42 N/A
	PUBLICITY ISSUED DESCRIPTION 45
7 8	9 10 719
810	6 15 NAME OF PREPARER J. J. Espey PHONE: 609-935-0998