



ATTACHMENT TO LER# 81-019/03L-0

SUPPLEMENT TO CAUSE DESCRIPTION

THIS WAS NOT NOTICED DURING THE TEST SINCE AN ISOLATION VALVE UPSTREAM OF THE TEE WAS SHUT.

TO PREVENT RECURRENCE OF THIS TYPE OF INCIDENT, THE INTEGRATED LEAKRATE TEST PROCEDURE HAS BEEN MODIFIED TO VERIFY THE PROPER SYSTEM ISOLATION OF TEST AND INSTRUMENT CONNECTIONS IN THE VICINITY OF THE ILRT INSTRUMENT SETUP. THE PERFORMANCE ENGINEERS ALSO RECEIVED ADDITIONAL TRAINING, EMPHASIZING THE IMPORTANCE OF REPLACING PIPE CAPS OR PLUGS WHICH ARE REMOVED FOR TEST PURPOSES.