

APPENDIX A

NOTICE OF VIOLATION

Canberra Industries
Meriden, Connecticut 06450

Docket No.: 30-08562
License No.: 06-15099-01

As a result of the inspection conducted on February 26, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violation was identified:


- A. Condition 13.A(1) of your license requires that you test your sealed sources containing byproduct material for leakage and/or contamination at intervals not to exceed six months.

Contrary to this requirement, you failed to test your sealed source containing iron-55 for contamination or leakage from February 16, 1980 to January 19, 1981, an interval of more than six months.

This is a Severity Level V Violation (Supplement VII).

Pursuant to the provisions of 10 CFR 2.201, Canberra Industries is hereby required to submit to this office within twenty-five days of the date of this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Under the authority of Section 182 of the Atomic Energy Act of 1954, as amended, this response shall be submitted under oath or affirmation.

Dated 02 APR 1981


John D. Kinneman, Chief
Materials Radiological Protection
Section