

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N J S G S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5
7 8 9 14 15 25 26 30 37 CAT 58

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 2 7 2 7 0 5 2 1 8 1 8 0 6 1 9 8 1 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

0 2 Action Statement 3.8.1.1a was entered at 0836 hours on May 21, 1981, due to the loss
0 3 of number 12 and 22 Station Power Transformers. This loss of power caused a partial
0 4 blackout of both Unit 1 and 2. This occurrence constituted operation in a degraded
0 5 mode IAW Technical Specification 6.9.1.9b.
0 6
0 7
0 8

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
E B 11 B 12 C 13 C K T L R K 14 F 15 Z 16
7 8 9 10 11 12 13 18 19 20
17 LER NO. REPORT NUMBER 8 1 0 5 5 0 3 L 0
21 22 23 24 26 27 28 29 30 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
H 18 Z 19 B 20 C 21 0 0 1 6 Y 23 N 24 L 25 2 9 9 9 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

1 0 Loss of power was caused by design deficiency in the No. 3 Unit Generator Breaker.
1 1 Power was restored and Action Statement 3.8.1.1a was terminated at 0918 hours on
1 2 May 21, 1981.
1 3
1 4

1 5 FACILITY STATUS C 28 0 2 8 29 N/A 30 METHOD OF DISCOVERY 31 Operator Observation 32
7 8 9 10 12 13 44 45 46 80
1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
7 8 9 10 11 44 45 80
1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
0 0 0 37 Z 38 N/A
7 8 9 11 12 13 80
1 8 PERSONNEL INJURIES NUMBER DESCRIPTION 41
0 0 0 40 N/A
7 8 9 11 12 80
1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43
Z 42 N/A
7 8 9 10 80
2 0 PUBLICITY ISSUED DESCRIPTION 45
N 44 N/A
7 8 9 10 68 69 80

8107060289 810619
PDR ADOCK 05000272
S PDR

J. J. Espey

PHONE 609-935-0993