

U.S. NUCLEAR REGULATORY COMMISSION

REGION III

Reports No. 50-456/90003(DRSS); 50-457/90003(DRSS)

Docket Nos. 50-456; 50-457

Licenses No. NPF-72; NPF-77

Licensee: Commonwealth Edison Company  
Post Office Box 767  
Chicago, IL 60690

Facility Name: Braidwood Nuclear Power Station, Units 1 and 2

Inspection at: Braidwood Station

Inspection Conducted: January 22-26, 1990

Inspectors: James Belanger  
James L. Belanger  
Senior Physical Security Inspector

2/13/90  
Date

G. M. Christoffer  
G. M. Christoffer  
Physical Security Inspector

2/13/90  
Date

Approved By: James R. Creed  
James R. Creed, Chief  
Safeguards Section

2/13/90  
Date

Inspection Summary

Inspection conducted on January 22-26, 1990 (Reports No. 50-456/90003(DRSS); 50-457/90003(DRSS))

Areas Inspected: A routine, unannounced physical security inspection involving TI 2515/102 (SIMS No. MPA L9-07) "Land Vehicle Bomb Contingency Procedure Verification;" management support; power supply; training and qualification; security plan/implementation procedures; management effectiveness; security organization; records and reports; testing and maintenance; assessment aids; training and qualification - general requirements; and licensee actions on previous Inspection findings.

Results: The licensee was found to be in compliance with NRC requirements in the areas examined except for the following areas:

Testing and Maintenance: The licensee failed to properly secure vital area doors (see Section 6 of Report Details). (Details Safeguards Information.)

9002270120 900213  
PDR ADOCK 05000456  
Q PNU

Enclosure Contains  
SAFEGUARDS INFORMATION  
Do not disseminate this  
information without  
written permission

The following noncited violations (NCV) were reviewed during this inspection:

Records and Reports:

The license failed to maintain an adequate vital area barrier (see Section 5.b of Report Details).

The licensee failed to properly issue a Security Badge. (See Section 5.c of Report Details).

The licensee's security program was adequately managed. Licensee performance in implementing security program requirements is adequate.

Enclosure Contains  
SAFEGUARDING INFORMATION  
Upon Separation This  
Page Is Deactivated