

U.S. NUCLEAR REGULATORY COMMISSION

REGION III

Report No. 50-483/90004

Docket No. 50-483

License No. NPF-30

Licensee: Union Electric Company
P.O. Box 149 - Mail Code 400
St. Louis, MO 63166

Facility Name: Callaway County Nuclear Power Station, Unit 1

Inspection At: Callaway Site, Callaway County, Missouri
NRC Region III Office, Glen Ellyn, Illinois

Inspection Conducted: January 22-25, 1990, onsite
January 29 to February 8, 1990, in NRC Region III Office

Inspector: Gary L. Pirtle
Gary L. Pirtle
Physical Security Inspector

2/14/90
Date

Reviewed By: J. M. Christoffer for
James R. Creed, Chief
Safeguards Section

2/14/90
Date

Approved By: L. Robert Greger
L. Robert Greger, Chief
Reactor Programs Branch

2-15-90
Date

Inspection Summary

Inspection on January 22 to February 8, 1990 (Report No. 50-483/90004(DRSS))

Areas Inspected: Unannounced, routine physical security inspection of management effectiveness; security plans and procedures; assessment aids; access control - Personnel; vital area detection aids; contingency plan implementation; security program audits; protection of Safeguards Information; training and qualification; followup on previous inspection findings; and review of Generic Letter 89-07, "Land Vehicle Bomb Contingency Procedures" (SIMS Item MPA L9-07).

Results: The licensee was found to be in compliance with NRC requirements within the areas examined, except as noted below. An apparent violation was noted in reference to the protection of some Safeguards Information.

Protection of Safeguards Information: On three specific occasions, containers with Safeguards Information were not adequately secured during specified non-duty hours.

9003010226 900216
PDR ADOCK 05000483
PDC

Enclosure Contains
SAFEGUARDS INFORMATION
Upon Separation This
Page is Decontrolled

Planning for the land vehicle bomb threat had been completed by the licensee. An open item pertaining to a modification of a portion of the protected area fence was reviewed and closed.

Management of the security organization continues to be effective. The security section was very responsive to inspection findings requiring staff action.

(Details: SAFEGUARDS INFORMATION)