LICENSEE EVENT REPORT
CONTROC BLOCK:
10 1 N C B E P 1 2 0 0 - 10 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 CAT SE
ON'T SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
While an auxiliary operator was hanging a clearance on RHR pumps 2A and 2C, the Unit 2
[0] [control operator noticed that RHR pumps 2A and 2C were still energized. Anticipating a
problem, he contacted the auxiliary operator and found out that RHR pump 1A and 1C had
[0]5 [been deenergized causing Division LPCI to be inoperable for approximately 20 minutes.]
Unit 1 was in condition 1, Unit 2 was in condition 5. Technical Specifications 3.5.3.2,
3 7 [6.9.1.9b.
081
SYSTEM CAUSE CODE SUBCODE SUBC
TO LER RO EVENT YEAR SEQUENTIAL REPORT NO. CODE TYPE NO. OCCURRENCE REPORT NO. OCCURRENCE TYPE NO. O 1 7 9 10 10 1
ACTION FUTURE EFFECT SHUTDOWN TAKEN ACTION ON PLANT METHOD HOURS (22) ATTACHMENT NPRD-4 PRIME COMP. COMPONENT SUBMITTED FORM SUBMITTED FORM SUB-SUPPLIER MANUSACTURES
A (8) H (19) Z (20) Z (21) O O O O Y (23) Y (24) A (25) G O (8 O O O O O O O O O O O O O O O O O
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) [The control operator contacted the auxiliary operator and determined that the clearance]
listed Unit One (1) instead of Unit Two (2). RHR pump breakers for pumps 1A and 1C
were immediately racked back in and the clearance corrected. All personnel involved
were strongly counseled by the operating supervisor as to being particularly careful
[with unit references on aperwork. All operations personnel will be required (cont.)
FACILITY STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 STATUS POWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 A (31) Operator surveillance
ACTIVITY CONTENT 12 13 44 45 46 80
NA NA NA
MUMBERT TYPE DESCRIPTION 39
8 9 PERSONNEL INJURIES 13
IN DESCRIPTION (41) NA
LOSS OF OR DAMAGE TO FACILITY (43)
J 2 Z (42) NA
NAC USE ONLY
68 69 80 5
A. C. Tollison, Jr. (919) 457-6701

LER CONTINUATION -- RO 1-79-17

Facility: BSEP Unit #1

Event Date 4/17/79

to review this LER as a reminder of the necessity for proper identification of units on clearances.