

APPENDIX A

NOTICE OF VIOLATION

Duke Power Company
Catawba

License Nos. CPPR-116
& CPPR-117

Based on the NRC inspection July 28-August 1, 1980, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

- A. As required by 10 CFR 50, Appendix B, Criterion XIII and implemented by Duke Power Company's Topical Quality Report 1A and Construction Procedure Serial No. 371, scaffolds should not be attached to or placed on installed equipment.

Contrary to the above, on July 31, 1980:

1. Scaffold boards were on the auxiliary feedwater and component cooling water piping in the auxiliary building.
2. Safety related cable No. 1*CA529 was laying on the floor in the auxiliary building.

This is a deficiency applicable to CPPR-116 only.

- B. As required by 10 CFR 50, Appendix B, Criterion XIII and implemented by Duke Power Company's Topical Quality Report 1A which commits to ANSI N45.2.2 and Construction Procedure Serial No. 170, materials stored outdoors may be stored in well drained areas and on cribbing or equivalent to avoid trapping water.

Contrary to the above, on July 30, 1980, three (3) sections of safety related pipe in the storage area at the piping fab shop were in contact with the ground.

This is a deficiency applicable to CPPR-117 only.