


50-29
Telephone 617 366-9011

TWX
710-390-0739

YANKEE ATOMIC ELECTRIC COMPANY



20 Turnpike Road Westborough, Massachusetts 01581

October 17, 1980

United States Nuclear Regulatory Commission
Washington, D. C. 20555

Attention: Mr. Darrell G. Eisenhut, Director
Office of Nuclear Reactor Regulation
Division of Licensing

Dear Darrell:

During our meeting on October 9 I mentioned that we had received a seemingly large number of orders and 50.54" caliber letters thus far this year. The attached summary is a tabulation of these. It is interesting to note that these 38 pieces of correspondence were received in addition to some 153 other letters requiring action on our part. We are probably no less busy than other licensees and that is probably the reason for a groan every time your office hints of issuing another major piece of correspondence.

I hope this information is interesting and helpful to you.

Very truly yours,

YANKEE ATOMIC ELECTRIC COMPANY

D. W. Edwards
Director of Operational Projects

DWE/smw
Attachment

80 10240 506

P

Acc 5/1

Orders Received This Year To Date 11

Implement TMI Cat. A requirements by 1/31/80	1/2/80	YR, VY, MY
Install Recirculation Pump Trip	2/21/80	VY
Review Class I-E & Nonclass I-E Buses	4/4/80	YR
Environ. Qualification Electrical Equipment due Committed Date	8/29/80	YR, VY, MY
Modification of License Revision	9/19/80	YR, VY, MY

Correspondence Requiring Response Under 50.54" f" This Year 27

LWR Primary Coolant System Pressure Isolation Valves	2/23/80	YR, VY, MY
Class IE Equipment	1/14/80	VY, MY
Westinghouse Turbine Cracks	2/25/80	MY
Crystal River - 3 Event Information Request	3/6/80	MY
ESF Reset Controls	3/13/80	YR, VY, MY
Schedules Environmental Qualification Electrical Equipment	3/28/80	YR
BWR Jet Pump Assembly Failure	4/4/80	VY
Masonry Wall Design	5/8/80	YR, VY, MY
Decay Heat Removal System Operability	5/9/80	YR, VY, MY
BWR Jet Pump Assembly	5/13/80	VY
GE Low Pressure Turbines	5/16/80	VY
Possible Loss of Emergency Notification System with Loss Offsite Power	6/18/80	YR, VY, MY
Failure of Control Rods to Insert	7/3/80	VY
Supplement-Failure of Control Rods to Insert	7/18/80	VY
Seismic Design	8/4/80	YR
BWR Scram System	10/1/80	VY

Other Correspondence Requiring Response This Year 153

YR, VY, MY