Bailey Controls Company Docket No. 99900224/81-01

NOTICE OF VIOLATION

As a result of the inspection conducted on May 4-8, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violation was identified:

Paragraph 21.6 of Title 10, Part 21, of the Code of Federal Regulations, states in part, "Each individual partnership, corporation or other entity subject to the regulations in this part, shall post current copies of the following documents in a conspicuous position on any premises, within the United States where the activities subject to this part are conducted (1) the regulations in this part, (2) Section 206 of the Energy Reorganization Act of 1974, and (3) procedures adopted pursuant to the regulations in this part.

If posting of the regulations in this part or the procedures adopted pursuant to the regulations in this part is not practicable . . . in addition to posting Section 206, post a notice which describes the regulations/procedures, including the name of the individual to whom ports may be made, and states where they may be examined."

Contrary to the above, posting of 10 CFR Part 21, Section 206 of the Energy Reorganization Act of 1974 or an appropriate notice had not been accomplished in the fabrication area.

This is a Severity Level VI Violation (Supplement II).