

# LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | 25 | 26 | 27 | 28 | 29 | 30 | 31 | 32 | 33 | 34 | 35 | 36 | 37 | 38 | 39 | 40 | 41 | 42 | 43 | 44 | 45 | 46 | 47 | 48 | 49 | 50 | 51 | 52 | 53 | 54 | 55 | 56 | 57 | 58 | 59 | 60 | 61 | 62 | 63 | 64 | 65 | 66 | 67 | 68 | 69 | 70 | 71 | 72 | 73 | 74 | 75 | 76 | 77 | 78 | 79 | 80 | 81 | 82 | 83 | 84 | 85 | 86 | 87 | 88 | 89 | 90 | 91 | 92 | 93 | 94 | 95 | 96 | 97 | 98 | 99 | 100 |

T N S N P 1 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 56 35

REPORT SOURCE 1 6 0 5 10 10 0 3 2 7 7 0 2 1 6 8 1 8 0 7 2 7 8 1 9  
60 61 CROCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
On 6-29-81 it was discovered that a pipe hanger, 1-067-ERCW-042-2, had been removed from the 2" ERCW line to the 1A pipe chase cooler but had not been reinstalled. The hanger had been removed to perform a modification to install a spool piece in the line for the ERCW corrosion study. The event is reportable under 6.9.1.13.c of Sequovah Unit 1 Technical Specifications. There was no effect upon public health or safety. Previous Occurrences - None.

SYSTEM CODE W E (11) CAUSE CODE A (12) CAUSE SUBCODE C (13) COMPONENT CODE S U P P O R T (14) COMP SUBCODE A (15) VALVE SUBCODE Z (16)  
9 10 11 12 13 14 15 16 17 18 19 20  
LEAD/NO REPORT NUMBER 8 1 (21) SEQUENTIAL REPORT NO. 0 7 2 (22) OCCURRENCE CODE 0 3 (23) REPORT TYPE L (24) REVISION NO. 0 (25)  
21 22 23 24 25 26 27 28 29 30 31 32  
ACTION TAKEN A (33) FUTURE ACTION Z (34) EFFECT ON PLANT Z (35) SHUTDOWN METHOD Z (36) HOURS 0 0 0 0 (37) ATTACHMENT SUBMITTED N (38) NFRD 4 FORM 455 N (39) PRIME COMP. SUPPLIER L (40) COMPONENT MANUFACTURER X 9 9 9 (41)  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)  
The cognizant engineer failed to have the hanger reinstalled after completion of the spool piece installation since he did not consider reinstallation of the hanger a priority item. The hanger was reinstalled on 6-30-81. The cognizant engineer has been instructed on the importance of reinstalling all components as soon as possible.

FACILITY STATUS G (31) % POWER 0 0 0 0 (32) OTHER STATUS NA (33) METHOD OF DISCOVERY B (34) DISCOVERY DESCRIPTION QA Observation (35)  
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

ACTIVITY CONTENT RELEASED OF RELEASE Z (36) AMOUNT OF ACTIVITY NA (37) LOCATION OF RELEASE NA (38)  
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

PERSONNEL EXPOSURES NUMBER 0 0 (39) TYPE Z (40) DESCRIPTION NA (41)  
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

PERSONNEL NUMBER 0 0 0 (42) DESCRIPTION NA (43)  
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

LOSS OF OR DAMAGE TO FACILITY TYPE Z (44) DESCRIPTION NA (45)  
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

PUBLICITY ISSUED N (46) DESCRIPTION NA (47)  
9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

8108040626 810727  
PDR ADOCK 05000327  
S PDR  
NRC USE ONLY

Name of Preparer: Glenn B. Kirk/Mike R. Harding

Phone: (615) 842-8317